

**Sedgwick County, Kansas – Public Works, East Yard
Americans with Disabilities Act Transition Plan
(2200 S. Webb Road)**

December 2006



Prepared by

DMCG
Disability Management Consulting Group L.L.C.
(dba; ADA Accrediting and Consulting)
2801 Jonquil Place
Columbia, MO 65202

In conjunction with

Sedgwick County and the Wichita/Sedgwick County Access Advisory Board

Sedgwick County – ADA/504 Transition Plan – Public Works, East Yard - December 2006 Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access			Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)			
1. Parking	Accessible parking does not exist due to a dirt/grass/gravel surface.	4.5.2	ADAAG requires all accessible routes and spaces, including access aisles at accessible parking, to be stable, firm and slip-resistant. The existing gravel/grass surface does not meet this specification. Create accessible parking spaces, if other vehicles from the general public are allowed to park in this area, which meet ADAAG specifications.	L	L	M	10	\$2,000	(See Building Block 1 – Accessible Parking , for greater clarification).						
2. Restrooms- Both Men and Women’s Restrooms	The restrooms are totally inaccessible due to numerous barriers.	4.23	Inconsistencies include, but are not limited to, narrow stalls, no Braille signage at entrance doors, round door hardware on entrance doors, inappropriate faucet controls on lavatories, pipes exposed under lavatories, grab bars are missing, etc. In new construction, ADAAG requires all public restrooms to be fully accessible. However, this facility is not considered new construction, and therefore falls under the program access provisions of Title II. Each and every public restroom may not need to be made accessible according to program access. We recommend making these restrooms fully accessible, if it is technically feasible to do so, or create one fully accessible unisex restroom.	V L	L	M	11 12 13 14 15 16 17	\$8,000	See Building Block 9 – Accessible Restrooms , for more information						

Public Works, East Yard - Transition Plan - Conceptual Cost Projections

Total	\$10,000
Year One (Very High – VH)	\$0
Year Three (High - H)	\$0
Year Five (Medium - M)	\$0
Year Ten (Low - L)	\$2,000
Year Ten (Very Low - VL)	\$8,000