

SEDGWICK COUNTY, KANSAS DIVISION OF FINANCE PURCHASING DEPARTMENT

525 N. Main, Suite 823 ~ Wichita, KS 67203 Phone: 316 660-7255 Fax: 316 383-7055

http://sedgwickcounty.org/finance/purchasing.asp

Request for Bid
#14-0027
HOME Investment Partnerships Program
Sedgwick County Housing Department/SCKEDD
Homeowner Rehabilitation Program
Property located at 2109 E. Fairchild St., Park City, KS
Addendum #1

March 24, 2014

The following is to ensure that vendors have complete information prior to submitting a bid. Here are some clarifications regarding the Rehabilitation Program at 2109 E. Fairchild St., Park City, KS.

Questions and/or statements of clarification are in bold font, answers to specific questions are italicized.

Please use the Revised Bid Sheet attached when submitting your bid response.

Firms interested in submitting a bid, must respond with complete information and all supplementary materials and deliver on or before 1:45 p.m. (CDT), Tuesday, April 8, 2014. Late bids will not be accepted and will not receive consideration for final award.

PLEASE ACKNOWLEDGE RECEIPT OF THIS ADDENDUM ON THE BID RESPONSE PAGE.

Joe Thomas, C.P.M. Purchasing Director

Revised Bid Sheet for HOME Program RFB #14-0027

Client: Juanita Misquez

Address: 2109 E. Fairchild St., Park City, KS

Phone: 316-665-1190

| | Work Specifications: | <u>Labor</u> | <u>Materials</u> | | <u>Total</u> |
|---------|---|------------------|------------------|----|--------------|
| | Exterior Siding, Trim, Soffits, and Fascia | | | | |
| | Replace any damaged/deteriorated soffit, fascia and siding with new material. Paint the entire home. | | | | |
| | Porches, Walkways, Driveways | ., | | | : |
| | Replace damaged walkway from driveway to front porch and replace the step. | | | | |
| | Windows | | | | |
| | Remove the deteriorated basement window unit and install a new dual pane Low-E white vinyl window unit with screen panel. | | | | |
| Revised | Electrical | | | | |
| | Replace 2 exterior receptacles with GFCI and weatherproof box. | | | | |
| | Miscellaneous | | | | |
| | Remove and replace the existing deteriorated concrete pad for the A/C condensing unit. | | | | |
| | Total Project Cost | ··· · | | | |
| | | | - | -, | |
| | Contractor Name: | | | • | |
| | Contractor Signature: | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |